

03500.017608.



Cafe
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
HIROKI SUE, et al.) Examiner: R. Patel
Appl. No.: 10/633,037) Group Art Unit: 2838
Filed: August 4, 2003)
For: POWER SUPPLY CONTROL)
APPARATUS)
U.S. Patent No.: 6,952,357 B2)
Issued: October 4, 2005) July 25, 2006

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR
CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

07/27/2006 SDENB001 00000106 6952357

01 FC:1811

100.00 0P

AUG 1 2006

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,


John D. Maglyan
Attorney for Patentees
Registration No.: 56,867

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

CA_MAIN 116530v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,952,357 B2

DATED : October 4, 2005

INVENTOR(S) : Sue, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER PAGE:

(57) ABSTRACT, line 8, "lowered" should read -- lowered, --.

COLUMN 4:

Line 1, "Ti," should read -- T1, --.

COLUMN 5:

Line 5, "obtain" should read -- obtained --; and

Line 56, "(a)" should read -- (an --.

COLUMN 9:

Line 6, "again the" should read -- again of the --.

COLUMN 10:

Line 1, "again the" should read -- again of the --.

CA_MAIN 116528v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,952,357 B2No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,952,357 B2
DATED : October 4, 2005
INVENTOR(S) : Sue, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER PAGE:

(57) ABSTRACT, line 8, "lowered" should read -- lowered, --.

COLUMN 4:

Line 1, "Ti," should read -- T1, --.

COLUMN 5:

Line 5, "obtain" should read -- obtained --; and

Line 56, "(a)" should read -- (an --.

COLUMN 9:

Line 6, "again the" should read -- again of the --.

COLUMN 10:

Line 1, "again the" should read -- again of the --.

CA_MAIN 116528v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,952,357 B2

No. of add'l. copies
@ 30¢ per page